

SECTION 1 - Identity					
Product Name:	WAX WIRE ASSORTMENT		Manufacturer:	GROBET FILE CO OF AMERICA INC.	
Generic Name:			Address:	750 WASHINGTON AVE CARLSTADT, NJ 07024	
Chemical Family:			Manufacturer Phone #:	800-998-4467	
Formula			Spill, Leak, Fire, Exposure, Accident:	800-255-3924	
SECTION 2 - Ingredient Information					
Chemical Name	Wt. %	OSHA PEL	ACGIH	Other	CAS No.
N/A	N/A	N/A	N/A	N/A	N/A
SECTION 3 - Physical Characteristics			SECTION 4 - Fire & Explosive Hazard Data		
Boiling Point:	>600 F		Flash Point: (method used)	N/A	
Vapor Pressure: (mm Hg)	<0.1		Upper Explosion Limit:	N/A	
Vapor Density: (air = 1)	N/A		Lower Explosion Limit:	N/A	
Specific Gravity:	.930		Extinguishing Media:	USE WATER FOG, FOAM, DRY CHEMICAL OR CO2. DO NOT USE A DIRECT STREAM OF WATER. PRODUCT WILL FLOAT AND CAN BE REIGNITED ON SURFACE OF WATER.	
Melting Point:	N/A		Special Firefighting Procedures:	DO NOT ENTER CONFINED FIRE SPACE WITHOUT PROPER PROTECTIVE EQUIPMENT INCLUDING A NIOSH APPROVED SELF-CONTAINED BREATHING APPARATUS. COOL FIRE-EXPOSED CONTAINERS WITH WATER.	
Evaporation Rate:	BUTYL ACETATE=1 N/A		Unusual Fire & Explosion Hazards:	NONE	
Solubility in Water:	NEGLECTIBLE				
Appearance & Odor	BLUE SOLID W/CHARACTERISTIC ODOR				
SECTION 5 - Reactivity Data					
Stability:	STABLE		Hazardous Decomposition:	CARBON MONOXIDE, CARBON DIOXIDE AND UNIDENTIFIED ORGANIC COMPOUNDS MAY BE FORMED DURING COMBUSTION.	
Incompatibility (materials to avoid)	NONE		Hazardous Polymerization:	WILL NOT OCCUR	
SECTION 6 - Health Hazard Data					
CARCINOGENICITY	NPT: N/A	IARC MONOGRAPHS:	N/A	OSHA REGULATED:	N/A
EFFECTS OF OVEREXPOSURE			FIRST AID PROCEDURES		
Skin:	MOLTEN WAX MAY CAUSE BURNS		Skin:	IF HOT WAX STRIKES THE SKIN, DRENCH OR IMMERSE THE AREA IN WATER TO ASSIST COOLING. IF AVAILABLE, APPLY ICED WATER OR ICE PACKS TO THE BURNED AREA. DO NOT USE ICED WATER OR COLD PACKS IF THE BURNED AREA COVERS MORE THAN 10% OF THE BODY AS THIS MAY CONTRIBUTE TO SHOCK. DO NOT TRY TO REMOVE WAX FROM A BURN AFTER IT HAS COOLED. SEEK MEDICAL ATTENTION: IF COOL WAX CONTACTS SKIN, WASH THE AREA WITH WARM SOAPY WATER.	
Eyes:	MOLTEN WAX FUMES MAY CAUSE IRRITATION		Eyes:	FLUSH WITH WATER FOR AT LEAST 15 MINUTES. SEEK MEDICAL ATTENTION	
Inhalation:	MOLTEN WAX FUMES MAY CAUSE MILD UPPER RESPIRATORY IRRITATION		Inhalation:	REMOVE VICTIM TO FRESH AIR: SEEK MEDICAL ATTENTION.	

171-704,705

Ingestion: NON LIKELY	Ingestion: CONSULT MEDICAL PERSONNEL
SECTION 7 – Precautions for Safe Handling & Use	
In Case of Release or Spill:	USE CAUTIOUS JUDGEMENT WHEN CLEANING UP LARGE MOLTEN SPILLS. LARGE SPILLS: WEAR RESPIRATOR AND PROTECTIVE CLOTHING AS APPROPRIATE. SHUT OFF SOURCE OF LEAK IF SAFE TO DO SO. DIKE AND CONTAIN. ALLOW WAX TO COOL AND REMOVE AS A SOLID. SMALL SPILLS: ALLOW WAX TO COOL AND REMOVE AS A SOLID.
Waste Disposal Method:	PLACE IN AN APPROPRIATE DISPOSAL FACILITY IN COMPLIANCE WITH LOCAL REGULATIONS.
Handling & Storage:	N/A
Other Precautions:	N/A

SECTION 8 – Control Measures

Respiratory Protection: N/A	Eye Protection: N/A
Ventilation Requirements: N/A	Other Protections: AVOID BREATHING VAPORS, FUMES OR MIST.
Protective Gloves: N/A	

SECTION 9 – Additional Information

This company cannot anticipate all conditions of handling and use of this product. Therefore, this company accepts no responsibility for results obtained by the application of this information, or the safety and suitability of our products either alone or in combination with other products. It is the responsibility of the user to provide a safe workplace, using the health and safety information contained herein as a guide. This company will accept no liability for damages or loss incurred from the improper handling and use of this product.